

R&D INFINITE RESOURCES

(Company No: JM0584598-X)
No. 21.21-01, Jalan Masai Utama 2,
Taman Masai Utama,
81750 Masai, Johor.
Tel : 07-2556465
Fax : 07-2557465

D.O No: **RDO 00482**
Date: **29/09/2015**
Your P.O No:
Invoice No: **RDI 00472**
Terms: **30 days**
Page: **1 of 1**

DELIVERY ORDER

TO: JOHOR PORT BERHAD,
P.O BOX 151,
81707 PASIR GUDANG,
JOHOR, MALAYSIA.

Att: M&R Department

No	Item Code	Description	Qty
1		To supply mapower,tools,parts and consumables for rectification work on gantry Tc 18 -To carry out thorough inspection on gantry problem -To dismantle gantry motor and coupling from crane -To carry out repair work on coupling housing box -To supply new bolts -To install gantry motor,coupling and housing on crane -To do function test & commissioning	1 Lot

Goods/services received in good order,

R&D INFINITE RESOURCES


Mohd FAIRIZ IMAN

Receiver Chop and Signature



Authorised Signature

JohorPort
MAINTENANCE AND REPAIR DEPARTMENT
JOBSHEET

MACHINE <i>LC 2818</i>	H/METER		DATE IN	<i>28/9/15</i>	TIME IN	<i>11:20</i>	DOWNTIME CODE	PM	CM	STP
	OFF SET		DATE OUT		TIME OUT		☒ BDN	☐ ACC	☐ O	
	MMIS					WORK ORDER	<i>R 7316</i>			

√	AREA / LOCATION	SUB ASSET NO	√	AREA / LOCATION	SUB ASSET NO
1	AIRCONDITIONER		13	LIGHTING	
2	BOOM		14	MACHINERY HOUSE	
3	BRAKE		15	MAN LIFT	
4	CATENARY		16	POWER SUPPLY	
5	ELECTRICAL / ELECTRONICS		17	SKEW	
6	ENGINE		18	SPREADER	
7	FESTOON		19	STEERING	
8	GANTRY / AXLE & WHEEL		20	STRUCTURE / BODY / CHASSIS	
9	GENERATOR		21	TLS / ANTISWAY	
10	HEAD BLOCK		22	TRANSMISSION	
11	HOISTING / LOWERING		23	TROLLEY	
12	HYDRAULICS				

RTS REPLACEMENT					
Part Description	Stock Code	Qty	DN No	RN/EJO No	ISSUE No

ULTS / DESCRIPTION
Gantry Problem (R1)

ALL JOB DONE / FINDINGS
- Check and found bolt and nut for gearbox R1 broken.

REMARK BY SUPERVISOR/TECHNICIAN ON THE JOB TED BY <i>Norhisam Mustafa</i> SIGNATURE <i>[Signature]</i> JOHOR PORT BERHAD	REMARK BY JPB's OFFICER <i>Mounting bolt / nut damaged.</i> <i>- Tyre found / (Main cover Bent (Accident)).</i> <i>- To Repair / replace new bolt/nut (R1).</i> <i>- gearbox (R1) oil Leak (output shaft).</i> VERIFIED BY <i>[Signature]</i> NAME & SIGNATURE <i>T.A.</i> DESIGNATION JOHOR PORT BERHAD
--	---